

Expected tolerance when not mentioned is 0.1 mm

Holes threaded with M8 fine pitch 0.5mm

